

**Inspection Report**

Report No.: XYDA-150302  
 Supplier : XY-GLOBAL

Inspection Date: 1<sup>th</sup> Apr, 2015  
 Inspector: Leo

Inspection only for: PO . XYDA-150302 Item No. XY31CY022	<u>Inspection Result:</u> <b>PASS</b>
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY022	55000PCS	1% inspection	0pcs	No failure	55000pcs


**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :



**XY-GLOBAL** 深圳市真朴电子科技有限公司  
 XY Electronics Technology Co.,Ltd

Client Name	Product Type	Inspection Date	Inspector
XYDA-150302	XY31CY022	2015-04-01	Leo
Part No.	Lot/Production No.	Quantity	Lot/Production No.
XY31CY022	150302-001	55000	150302-001
Inspection Item	Inspection Method		
Appearance	Visual		
Dimension	Caliper		
Material	Material		
Test Result	Pass		
Inspector	Inspector		
Leo	Leo		

XY Electronics Technology Co., Ltd  
 150302-001

5. Product: 6. report

