

Inspection Report

Report No.: XYNK-130827
 Supplier : XY-GLOBAL

Inspection Date:15th Sep-, 2013
 Inspector:LEO

Inspection only for: PO . XYNK-130827 Item No.1460350	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1460350	1000Pcs	100% inspection	0pcs	No failure	1000Pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. Product:

