

**Inspection Report**

Report No.: XYGA-150309  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Apr., 2015  
 Inspector: LEO

Inspection only for: PO . XYGA-140309    Item No. XY21ZC049	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC049	5000pcs	7% inspection	0pcs	No failure	5000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
形状	
用途	
加工工程	
加工機	CNC加工機
加工時間	
加工費	
MOQ	
公差	+/- 0.01mm
リードタイム	T / T 50% 50% T / T
加工機	CNC加工機
加工工程	
加工機	
加工時間	20 25 T / T 50
加工費	CNC加工費
1. Name OEM CNC加工品	
2. Process CNC加工	
3. Material AL6061 AL6065 AL6063 AL7075 POM	
4. Surface nickel	
5. Tolerance +/- 0.01mm	
6. MOQ 100	
7. Specification OEM service	
8. Lead Time 25 30	
9. CNC加工機 accessories	
10. Austria EU	
11. ISO 9001	
ISO 9001	
ISO 9001	
3. surface finishment kinds available	
4. 加工機	
5. 加工機	
6. 加工機	
7. 加工機	
加工機	
CNC加工機	
CNC加工機	
CNC加工機 ISO9001	
CNC加工機	
CNC加工機 OEM加工品	