

Inspection Report

Report No.: XYSL-140611
 Supplier : XY-GLOBAL

Inspection Date: 10th Jul, 2014
 Inspector: Leo

Inspection only for: PO . XYSL-140611 Item No. XY11WD035	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD035	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. The test report</p>

製品名	製品名 OEM製品
材料	ADC12/A380
表面処理	nickle
公差	+/- 0.01
MOQ	100
納期	T / T 50% T / T
加工方法	CNC
品質管理	ISO 9001
1.Name	OEM
2.Process	CNC
3.Material	ADC12/A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM service
8.	25/30
9.	accessoried
10.	Austrial/EU
11.	ISO 9001
ISO	1. 10
2.	
3. sureface	finishment kinds available
4.	
5.	
6.	
7.	
8.	
9.	
10.	
11.	
ISO	9001
OEM	