

□□□□□□□□□□□□□□□□□□□□

Inspection Report

Report No.: 131126-046-V1
Supplier :

Inspection Date: 26th Nov 2013
Inspector: Ken Tung

Inspection only for: Item No. 401-01-046	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
U max Base	2500pcs	125pcs	5pcs	5pcs scratch on the surface	2500pcs

Appearance Inspection :
 No failure,
 5pcs scratch on the surface

Dimension Inspection:
 No failure , below measurement report for reference.

Leakage Test:
 No failure

Inspection Summary
 The inspection sample plan are follow AQL , 5pcs scratch on the surface.
 The result of inspection is acceptable.

Digital photo records :

1. Packing	2. Product
3. Product	4. item number
5. Product	6. Product
7 Product	8. Product
9. Defect- scratch on the surface	10. Carton

品名	ADC12 A380 CNC 加工品
数量	1000個
仕様	外径φ50mm 長さ50mm 公差±0.01mm
材質	ADC12 (Al-Si系)
加工方法	CNC 旋削加工
表面処理	ニッケルメッキ (nickle)
公差	±0.01mm
MOQ	100個
納期	受注後 10 営業日程度
梱包	10個/袋
検量機	デジタルマイクロメータ
1.Name	品名 CNC 加工品
2.Process	CNC 加工
3.品名	ADC12 A380
4.Surface	nickle 処理
5.Tolerance	±0.01mm
6.数量	100個
7.Specification	OEM 仕様
8.公差	±0.01mm
9.付属品	accessories あり
10.認証	Austrial EU
11.&NBSP	ISO 9001
品質管理	ISO 9001 認証済み
2.公差	±0.01mm
3 surface	finishment kinds available
4.数量	100個
5.公差	±0.01mm
6.数量	100個
7.公差	±0.01mm
品質管理	ISO 9001 認証済み
&NBSP	ISO 9001
OEM	加工品