

Inspection Report

Report No.: XYF-130830
 Supplier : XY-GLOBAL

Inspection Date:29th Sep, 2013
 Inspector:LEO

Inspection only for: PO . XYF-130830 Item No. 2543100	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
2543100	10000Set	100% inspection	0pcs	No failure	10000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product
3. Product:	4. Product:
5. Product :	6. inspection reports

品名	CNC 加工品CNC加工品CNC加工品CNC加工品CNC加工品CNC加工品CNC加工品
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM
寸法	
仕様	
加工方法	CNC加工
表面処理	gague
MOQ	
公差	+/- 0.01
リードタイム	T / T 50 / T 50
加工能力	CNC加工CNC加工CNC加工CNC加工
加工精度	CNC加工
加工速度	20-25 / T 50
加工機	CNC加工
1.Name OEM CNC 2.Process CNC 3.Material AL6061 AL6065AL6063AL7075POM 4.Surface nickle 5.Tolerance +/- 0.01 6.100 7.Specification OEM service 8.25 30 9.CNC accessoried 10.Austrial EU 11.ISO 9001	
ISO 1. 10	
2. sureface finishment kinds available	
3. 4	
5.	
6.	
7.	
CNC	
CNC	
CNC ISO9001	
CNC	
CNC OEM	