

**Inspection Report**

**Report No.:** XYND-140512  
**Supplier :** XY-GLOBAL

**Inspection Date:** 5<sup>th</sup> Jun, 2014  
**Inspector:** Leo

Inspection only for: PO . XYND-140512 Item No.30013467	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
30013467	10000PCS	1% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
仕様	ADC12 A380
数量	1000個
納期	約 20-25日
加工方法	CNC加工
公差	+/- 0.01mm
表面処理	ニッケルメッキ
検出	100%
仕様書	OEM仕様書
梱包	25個/箱
付属品	accessories
認証	Austrial EU ISO 9001
備考	
ISO	1. 10mm
2.	
3. surface	finishment kinds available
4.	
5.	
6.	
7.	
8.	
9.	
10.	
11.	
ISO	ISO9001
OEM	