



**Inspection Report**

Report No.: XYSK-140503  
Supplier : XY-GLOBAL

Inspection Date: 1<sup>th</sup> Jun, 2014  
Inspector: Leo



Inspection only for: PO . XYSK-140503 Item No. XY11WD009	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD009	5000PCS	1% inspection	0pcs	No failure	5000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
--	--

<p>1. Packing</p> 	<p>2. Product</p> 
---	---

<p>3. Product</p> 	<p>4 Product</p> 
---	--

5. Product: 6. Dimensions report

