

Inspection Report

Report No.: XYKB-140518
Supplier: XY-GLOBAL






Inspection Date: 12th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140518 Item No. XY72YM014	Inspection Result: PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM014	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report:

品名	加工品 加工品 加工品 加工品 OEM加工品
品名	ADC12 A380
品名	
品名	
品名	CNC 加工品
品名	加工品 gague 加工品 CNC加工品
MOQ	加工品
公差	+/- 0.01
公差	T / T 50 加工品 50 T / T; 加工品
公差	CNC加工品 CNC加工品 加工品 加工品
公差	加工品 加工品 加工品 加工品
公差	加工品
公差	20-25 T / T 50 加工品
公差	加工品
1.Name	OEM加工品
2.Process	CNC加工品
3.Material	ADC12 A380
4.Surface	nickle 加工品
5.Tolerance	+/- 0.01 加工品
6.	100 加工品
7.Specification	OEM serice 加工品
8.	25 30 加工品
9.	accessoried 加工品
10.	Austrial EU 加工品
11.	ISO 9001
ISO	1. 10 加工品
2.	加工品
3. sureface	finishment kinds available 加工品
4.	加工品
5.	加工品
6.	加工品
7.	加工品
8.	加工品
9.	加工品
10.	ISO9001
11.	加工品
OEM	加工品