

□□□□□□□□□□□□□□□□

Inspection Report

Report No.: XYS-130311
Supplier: XY-GLOBAL

Inspection Date: 14th Apr, 2013
Inspector: Leo

Inspection only for: PO . XYS-130311 Item No.XY-1320354	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1320354	5000PCS	10% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

Item	Part Name: OEM Component
Material	ADC12/A380
Process	CNC Machining
Surface	nickle
Tolerance	+/- 0.01mm
MOQ	100 pieces
Lead Time	T / T 50%
Payment	CNC Machining
Quality	ISO 9001
1.Name	OEM
2.Process	CNC Machining
3.	ADC12/A380
4.Surface	nickle
5.Tolerance	+/- 0.01mm
6.	100 pieces
7.Specification	OEM
8.	25-30 days
9.	accessories
10.	Austrial EU
11.	ISO 9001
	OEM
	ISO 9001
	2
	3 surface finishment kinds available
	4
	5
	6
	7
	OEM
	 ISO 9001
	ISO 9001
	OEM