

Inspection Report

Report No.: XYKB-140509
Supplier : XY-GLOBAL

Inspection Date: 4th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140509 Item No. XY72YM005	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM005	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

									
1. Packing	2. Product								
									
3. Product	4 Product								
	<p>XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Inspection Part: XY72YM005</td> <td>Product Type: XY72YM005</td> <td>Inspection Date: 2014.6.4</td> <td>Inspector: Leo</td> </tr> <tr> <td>Lot No: XY72YM005</td> <td>Quantity: 8000PCS</td> <td>Inspection Result: PASS</td> <td>Customer: XY-GLOBAL</td> </tr> </table> <p>Inspection Summary: No failure</p> <p>Inspection Details: No failure</p> <p>Inspection Results: No failure</p> <p>Inspection Conclusion: No failure</p>	Inspection Part: XY72YM005	Product Type: XY72YM005	Inspection Date: 2014.6.4	Inspector: Leo	Lot No: XY72YM005	Quantity: 8000PCS	Inspection Result: PASS	Customer: XY-GLOBAL
Inspection Part: XY72YM005	Product Type: XY72YM005	Inspection Date: 2014.6.4	Inspector: Leo						
Lot No: XY72YM005	Quantity: 8000PCS	Inspection Result: PASS	Customer: XY-GLOBAL						
5. Product:	6. Dimensions report:								

品名	ステンレス鋼 CNC加工品 OEM受注品
品番	ADC12 A380
材質	ステンレス鋼
仕様	標準仕様
加工方法	CNC加工
表面処理	ニッケルメッキ
公差	+/- 0.01
MOQ	100個
納期	20-25日
備考	ISO 9001
1. Name	OEM受注品
2. Process	CNC加工
3. Material	ADC12 A380
4. Surface	ニッケルメッキ
5. Tolerance	+/- 0.01
6. Specification	OEM受注品
7. Accessoried	付属品
8. ISO 9001	ISO 9001
9. Surface finishment	kindls available
10. ISO 9001	ISO 9001
11. OEM	OEM受注品