

Inspection Report

Report No.: XYDA-150304
 Supplier : XY-GLOBAL

Inspection Date: 1th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYDA-150304 Item No. XY31CY024	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY024	23000PCS	1% inspection	0pcs	No failure	23000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



