

**Inspection Report**

Report No.: XYKB-140519  
Supplier : XY-GLOBAL






Inspection Date: 14<sup>th</sup> Jun, 2014  
Inspector: Leo

Inspection only for: PO . XYKB-140519 Item No. XY72YM015	<u>Inspection Result:</u> <b>PASS</b>
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM015	1000PCS	1% inspection	Opes	No failure	1000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

																	
1. Packing	2. Product																
																	
3. Product	4 Product																
	<p style="text-align: center;"><b>XY-GLOBAL</b> 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Inspection Report</td> <td>Product Name</td> <td>Inspector</td> <td>Inspection Date</td> </tr> <tr> <td>XY72YM015</td> <td>XY72YM015</td> <td>Leo</td> <td>2014-6-14</td> </tr> </table> <p>Inspection Result: <b>PASS</b></p> <p>Inspection Details:</p> <table border="1"> <thead> <tr> <th>Item</th> <th>Quantity</th> <th>Defect</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>XY72YM015</td> <td>1000</td> <td>0</td> <td></td> </tr> </tbody> </table> <p>Inspection Summary: All items passed inspection.</p>	Inspection Report	Product Name	Inspector	Inspection Date	XY72YM015	XY72YM015	Leo	2014-6-14	Item	Quantity	Defect	Remarks	XY72YM015	1000	0	
Inspection Report	Product Name	Inspector	Inspection Date														
XY72YM015	XY72YM015	Leo	2014-6-14														
Item	Quantity	Defect	Remarks														
XY72YM015	1000	0															
5. Product:	6. Dimensions report:																

