

Inspection Report

Report No.: XYA-140514
Supplier : XY-GLOBAL

Inspection Date: 10th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYA-140514 Item No.200-10-049	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-10-049	6000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
仕様	ADC12 A380
数量	1000個
納期	約 20-25日
加工方法	CNC加工
公差	+/- 0.01mm
表面処理	ニッケルメッキ
検出	100%
仕様書	OEM仕様書
梱包	10個/箱
送料	別途見積
備考	
1. Name: ADC12 A380 CNC加工品	
2. Process: CNC加工	
3. Material: ADC12 A380	
4. Surface: ニッケルメッキ	
5. Tolerance: +/- 0.01mm	
6. 検出: 100%	
7. Specification: OEM仕様書	
8. 納期: 約 20-25日	
9. 付属品: 付属品あり	
10. 規格: Austrial EU	
11. 認証: ISO 9001	
ISO 1. 10mm	
2. 仕様: 仕様書	
3. 表面処理: finishment kinds available	
4. 検出: 4%	
5. 納期: 納期	
6. 送料: 送料	
7. 備考: 備考	
8. 検出: 検出	
9. 仕様書: 仕様書	
10. ISO9001: ISO9001	
11. OEM: OEM	