XY-GLOBAL XY Electronics Technology Co., Ltd

Inspection Report

Report No.: XYI-140322
Supplier : **XY-GLOBAL**

Inspection Date: 19th Apr, 2014
Inspector: Leo

Inspection only for:	Inspection Result:
PO . **XYI-140322** Item No.143045	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
143045	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing

2. Product

3. Product

4 Product

5. Product:

6. Product:

7. Product:



8. Report:

[illegible]	[illegible] [illegible]OEM[illegible]
[illegible]	[illegible]ADC12[illegible]A380[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	CNC[illegible]CNC[illegible]
[illegible]	[illegible]gague[illegible]
MOQ	[illegible]
[illegible]/[illegible]	+/- 0.01[illegible]
[illegible]	T / T 50[illegible]50[illegible]T / T;[illegible]
[illegible]	CNC[illegible]·[illegible]CNC[illegible]
[illegible]	[illegible]
[illegible]	[illegible]
[illegible]	20-25 [illegible]T / T 50[illegible]
[illegible]	[illegible]

1.Name[illegible] [illegible]OEM[illegible]
2.Process[illegible] [illegible]CNC[illegible]
3.[illegible]ADC12[illegible]A380[illegible]
4.Surface[illegible]nickle[illegible]
5.Tolerance[illegible]+/- 0.01[illegible]
6[illegible]100[illegible]
7.Specification[illegible]OEM[illegible]
8[illegible]25-30[illegible]
9[illegible]accessoried[illegible]
10[illegible]Austrial[illegible]EU[illegible]
11 [illegible]ISO 9001
[illegible]
ISO[illegible]1[illegible]10[illegible]
2[illegible]
3 sureface[illegible]finishment[illegible]kindls[illegible]abailable[illegible]
[illegible]4[illegible]
5[illegible]
[illegible]6[illegible]
7[illegible]
[illegible]
[illegible] [illegible]
[illegible]
[illegible]ISO9001
[illegible]
OEM[illegible]