

Inspection Report

Report No.: XYK-140524
Supplier : XY-GLOBAL

Inspection Date: 20th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140524 Item No.XY-141690	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-141690	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	铝合金 铝合金 CNC 加工 OEM 加工
规格	ADC12 A380
数量	10000
用途	汽车零部件
材料	铝合金
工艺	CNC 加工
表面处理	阳极氧化
MOQ	1000
公差	+/- 0.01
交期	T / T 50% T / T
包装	CNC 加工
认证	ISO 9001
产地	中国
重量	20-25g
其他	
1.Name	铝合金 OEM 加工
2.Process	CNC 加工
3.规格	ADC12 A380
4.Surface	nickle 表面处理
5.Tolerance	+/- 0.01
6.数量	10000
7.Specification	OEM 加工
8.重量	25-30g
9.其他	accessories
10.认证	Austrial EU
11.&NBSP	ISO 9001
ISO	10
2.	
3.sureface	finishment kinds available
4.	
5.	
6.	
7.	
ISO	
&NBSP	
ISO	9001
OEM	