

Inspection Report

Report No.: XYWD-140705
 Supplier : XY-GLOBAL

Inspection Date: 28th July, 2014
 Inspector: Leo

Inspection only for: PO . XYWD-140705 Item No. XY31SY49	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY49	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. report</p>

品名	CNC加工 部品加工CNC加工部品加工CNC加工部品加工CNC加工部品加工CNC加工部品加工CNC加工部品加工CNC加工部品加工
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
仕様	図面指定
数量	1部
納期	1週間以内
公差	CNC加工 0.01mm以内
表面処理	ニッケルめっき
MOQ	100個
公差	+/- 0.01mm
リードタイム	T / T 50% T / T 50%
加工方法	CNC加工
加工精度	0.01mm以内
公差	±0.01mm
加工方法	CNC加工
1.Name OEM CNC加工	
2.Process CNC加工	
3.Material AL6061 AL6065 AL6063 AL7075 POM	
4.Surface ニッケルめっき	
5.Tolerance +/- 0.01mm	
6.数量 100個	
7.Specification OEM service	
8.納期 25日/30日	
9.加工方法 CNC加工 accessories	
10.認証 Austrial EU	
11.規格 ISO 9001	
ISO 1. 10mm以内	
2.仕様 図面指定	
3. surface finishment kinds available	
4. 数量	
5. 納期	
6. 公差	
7. 加工方法	
加工精度	
CNC加工	
CNC加工	
CNC加工 ISO9001	
CNC加工	
CNC加工 OEM加工	