

□□□□□□□□□□□□□□□□□□

Inspection Report


Report No.: XYS-130509
Supplier : XY-GLOBAL

Inspection Date: 03th Jun, 2013
Inspector: Leo

Inspection only for: PO . XYS-130509 Item No.XY-CT-D-049	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-049	6000PCS	5% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	高精度 超精密加工部品 各種加工部品OEM
品番	品番 ADC12 A380
材質	鋼 鋁
用途	各種加工部品
加工方法	各種加工部品
加工機	CNC 各種加工部品 CNC
加工精度	高精度加工部品 gague
MOQ	100
公差	+/- 0.01
納期	T / T 50 50 T / T
加工機	CNC 各種加工部品 CNC
加工精度	高精度加工部品
加工機	各種加工部品
納期	20-25 T / T 50
加工機	各種加工部品
1.Name 高精度超精密加工部品	
2.Process 各種加工部品 CNC	
3.品番 ADC12 A380	
4.Surface 各種加工部品 nickel	
5.Tolerance +/- 0.01	
6.品番 100	
7.Specification OEM	
8.品番 25-30	
9.品番 accessoried	
10.品番 Austrial EU	
11 ISO 9001	
ISO 10	
2	
3 surface finishment kinds available	
4	
5	
6	
7	
ISO 9001	
OEM	