

Inspection Report

Report No.: XYKI-140314
Supplier : XY-GLOBAL

Inspection Date: 15th Apr, 2014
Inspector: Leo

Inspection only for: PO . XYKI-140314 Item No.3500097	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3500097	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品 OEM受注品
品番	ADC12 A380
材質	ADC12
仕様	表面処理: ニッケルメッキ
公差	±0.01mm
MOQ	100個
納期	T/T 50% 前払い / T/T 100% 前払い
加工方法	CNC加工
表面処理	ニッケルメッキ
公差	±0.01mm
納期	20-25日
備考	
1. Name: ADC12 A380 CNC加工品 OEM受注品	
2. Process: CNC加工	
3. Material: ADC12 A380	
4. Surface: ニッケルメッキ	
5. Tolerance: ±0.01mm	
6. MOQ: 100個	
7. Specification: OEM受注品	
8. 納期: 25-30日	
9. 表面処理: ニッケルメッキ	
10. 公差: ±0.01mm	
11. ISO 9001	
ISO 9001:2015	
2. 表面処理: ニッケルメッキ	
3. 表面処理: finishment kinds available	
4. 公差: ±0.01mm	
5. 納期: 20-25日	
6. 備考:	
7. 加工方法: CNC加工	
ISO 9001	
OEM受注品	