

Inspection Report





Report No.: XYNK-140514
Supplier: XY-GLOBAL

Inspection Date: 7th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYNK-140514 Item No.40010870	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
40010870	6000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
仕様	ADC12 A380
数量	100個
納期	約 20-25日
加工方法	CNC加工
公差	+/- 0.01mm
表面処理	ニッケルメッキ
検出	100%
仕様書	OEM仕様書
梱包	25個/箱
備考	accessories
規格	Austrial EU
品質	ISO 9001
ISO	1. 10
2.	
3. surface	finishment kinds available
4.	
5.	
6.	
7.	
品質	
品質	
品質	ISO9001
品質	
OEM	