

□□□□□□□□ADC12□□·□□□□□□

Inspection Report






Report No.: XYS-130928
Supplier : XY-GLOBAL

Inspection Date: 25th Oct, 2013
Inspector: Leo

Inspection only for: PO . XYS-130920 Item No.3240100	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3240100	3000PCS	5% inspection	0pcs	No failure	3000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	铝合金 CNC加工零件 OEM
规格	ADC12 A380
数量	10000
用途	汽车零部件
材料	ADC12
工艺	CNC 加工
表面处理	阳极氧化
MOQ	1000
公差	+/- 0.01
交期	T / T 50% T / T
工厂	CNC 加工
认证	ISO 9001
包装	20-25 个 / 箱
其他	
1.Name	铝合金 CNC加工零件 OEM
2.Process	CNC 加工
3.规格	ADC12 A380
4.Surface	阳极氧化
5.Tolerance	+/- 0.01
6.数量	10000
7.Specification	OEM
8.交期	25-30 天
9.其他	accessories
10.认证	Austrial EU
11.&NBSP	ISO 9001
ISO	10
2.	
3.sureface	finishment kinds available
4.	
5.	
6.	
7.	
ISO	
&NBSP	
ISO	9001
OEM	