

Inspection Report

Report No.: XYF-130814
Supplier : XY-GLOBAL

Inspection Date: 6th Sep-, 2013
Inspector: LEO

| | |
|---|-----------------------------------|
| Inspection only for: PO . XYF-130814 Item No. screw | Inspection Result: PASS |
|---|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| screw | 10000Set | 100% inspection | 0pcs | No failure | 10000Set |

| |
|--|
| Appearance Inspection : No failure, |
| Dimension Inspection: No failure , below measurement report for reference. |
| Assembly Test: No failure |
| Inspection Summary The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|--|
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. inspection reports |

