

**Inspection Report**

**Report No.:** XYF-130818

**Supplier :** XY-GLOBAL

**Inspection Date:** 10<sup>th</sup> Sep, 2013

**Inspector:** LEO

Inspection only for:	Inspection Result:
PO . XYF-130818      Item No. long screw	PASS

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
long screw	15000Set	100% inspection	0pcs	No failure	15000Set

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

**Digital photo records :**



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :

podmis									
Inspection Report									
Report No. XYF-130818									
Inspector: LEO									
Date: 10 Sep 2013									
Item: long screw									
Lot: 15000Set									
Sample Size: 100%									
Defect Found: 0									
Defects Description: No failure									
Acceptable Q'ty: 15000Set									
Inspection Summary: The inspection sample plan is 100% inspection.									

6. inspection reports

	CNC
	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
	CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 T / T
	CNC CNC CNC CNC
	CNC
	20-25 T / T 50
	CNC
1.Name  OEM CNC	
2.Process CNC	
3.Material AL6061 AL6065 AL6063 AL7075 POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6. 100	
7.Specification OEM serice	
8. 25 30	
9. CNC accessoried	
10. Austrial EU	
11. ISO 9001	
ISO 1. 10	
2.	
3. sureface finishment kinds available	
4	
5.	
6.	
7.	
CNC	
CNC	
CNC ISO9001	
CNC	
CNC OEM	