

Inspection Report

Report No.: XYKB-140512
 Supplier : XY-GLOBAL


Inspection Date: 8th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYKB-140512 Item No. XY72YM008	<u>Inspection Result:</u> PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM008	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report:

