

Inspection Report

Report No.: XYNK-130804
Supplier : XY-GLOBAL

Inspection Date: 5th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYNK-130804 Item No.400-02-353	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-02-353	3000PCS	100% inspection	0pcs	No failure	3000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	CNC加工 各種機械部品 CNC加工 各種機械部品 CNC加工 各種機械部品 CNC加工 各種機械部品 CNC加工 各種機械部品 CNC加工 各種機械部品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
仕様	各種仕様
用途	各種用途
加工方法	CNC加工
表面処理	各種表面処理 (gauge)
MOQ	100個
公差	+/- 0.01mm
納期	T / T 50% 50% T / T
加工精度	CNC加工 各種機械部品 CNC加工 各種機械部品 CNC加工 各種機械部品
加工能力	各種加工能力
加工時間	20-25日 T / T 50%
加工費用	CNC加工
1. Name 各種 OEM CNC加工	
2. Process 各種 CNC加工	
3. Material AL6061 AL6065 AL6063 AL7075 POM	
4. Surface 各種表面処理 (nickle)	
5. Tolerance +/- 0.01mm	
6. 各種仕様 100個	
7. Specification OEM service	
8. 各種仕様 25 30個	
9. 各種仕様 CNC加工 accessoried	
10. 各種仕様 Austria EU	
11. 各種仕様 ISO 9001	
ISO 1. 10個	
2. 各種仕様	
3. surface finishment kinds available	
4. 各種仕様	
5. 各種仕様	
6. 各種仕様	
7. 各種仕様	
各種仕様	
CNC加工 各種機械部品	
CNC加工 各種機械部品	
CNC加工 ISO9001	
CNC加工 各種機械部品	
CNC加工 OEM 各種機械部品	