

Inspection Report

Report No.: XYS-130315
Supplier : XY-GLOBAL

Inspection Date:12th Apr, 2013
Inspector: Leo

Inspection only for: PO . XYS-130315 Item No.XY-1300270	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1300270	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

ชื่อ	บริษัท ออโต้แมค จำกัด OEM
ประเภท	ADC12 A380
วัสดุ	อลูมิเนียม
ขนาด	ตามแบบร่าง
กระบวนการ	CNC
MOQ	100
ความแม่นยำ	+/- 0.01
ระยะเวลา	T / T 50% T / T
สถานที่	CNC
การรับประกัน	ตามเงื่อนไข
ราคา	20-25 \$ T / T 50%
อื่นๆ	
1.Name	บริษัท ออโต้แมค จำกัด
2.Process	CNC
3.วัสดุ	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.จำนวน	100
7.Specification	OEM
8.ขนาด	25-30
9.การรับประกัน	accessoried
10.มาตรฐาน	Austrial EU
11.&NBSP	ISO 9001
ISO	1 10
2.	
3.sureface	finishment kinds available
4.	
5.	
6.	
7.	
ISO	
&NBSP	
ISO	9001
OEM	