

Inspection Report

Report No.: XYSL-140620
 Supplier : XY-GLOBAL


Inspection Date: 25th Jul, 2014
 Inspector: Leo

Inspection only for: PO . XYSL-140620 Item No. XY11WD042	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD042	10000PCS	5% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. The test report</p>

名前	ご注文の品名は、OEM製品です。
材料	ADC12/A380
表面処理	ニッケル
公差	+/- 0.01mm
仕様	T / T 50 / T / T
MOQ	100個
リードタイム	20-25日 / T / T 50日
ISO	ISO 9001
1. Name	OEM
2. Process	CNC
3. Material	ADC12/A380
4. Surface	nickel
5. Tolerance	+/- 0.01
6. MOQ	100
7. Specification	OEM service
8. Lead Time	25-30 days
9. Accessoried	accessoried
10. Certification	Austrial / EU
11. ISO	ISO 9001
ISO	1. 10
2. sureface	finishment kinds available
3. 4. 5. 6. 7.	
ISO	ISO 9001
OEM	OEM