

Inspection Report

Report No.: XYSK-140612
 Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014
 Inspector: Leo

Inspection only for: PO . XYSK-140612 Item No. XY31SY012	Inspection Result: PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY012	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	 
5. Product:	6. report

