

**Inspection Report**

Report No.: XYNK-130809  
 Supplier : XY-GLOBAL

Inspection Date:10<sup>th</sup> Sep-, 2013  
 Inspector:LEO

Inspection only for: PO . XYNK-130809    Item No.1402289	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1402289	6000Pcs	100% inspection	0pcs	No failure	6000Pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	ADC12 A380 CNC加工品 OEM受注品
品番	ADC12 A380
材質	ADC12
仕様	表面処理: ニッケルメッキ
公差	±0.01
MOQ	100個
納期	T/T 50% 前払い / T/T 100% 納品後
加工方法	CNC加工
表面処理	ニッケルメッキ
公差	±0.01
納期	20-25日
品質保証	ISO 9001
1.Name	品名
2.Process	CNC加工
3.Material	ADC12 A380
4.Surface	nickle
5.Tolerance	±0.01
6.	100個
7.Specification	OEM service
8.	25 30
9.	accessories
10.	Austrial EU
11.	ISO 9001
ISO	1. 10
2.	
3. surface	finishment kinds available
4.	
5.	
6.	
7.	
品質保証	ISO 9001
OEM	