

Inspection Report

Report No.: XYN-140616
Supplier : XY-GLOBAL







Inspection Date: 11th July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140616 Item No.142078	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142078	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

