

□□□□□Preicse□□□□□□□

Inspection Report

Report No.: XYS-130313
 Supplier : XY-GLOBAL

Inspection Date: 12th Apr, 2013
 Inspector: Leo

Inspection only for: PO . XYS-130313 Item No.XY-1300260	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1300260	1000PCS	5% inspection	0pcs	No failure	1000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	铝合金 CNC加工 OEM
规格	ADC12 A380
数量	10000
用途	汽车零部件
材料	铝合金
工艺	CNC 加工
表面处理	阳极氧化
MOQ	1000
公差	+/- 0.01
交期	T / T 50% T / T
包装	CNC 加工
认证	ISO 9001
产地	中国
重量	20-25g
其他	
1.Name 铝合金 OEM	
2.Process CNC 加工	
3.规格 ADC12 A380	
4.Surface 阳极氧化	
5.Tolerance +/- 0.01	
6.数量 10000	
7.Specification OEM	
8.重量 25-30g	
9.其他 accessories	
10.认证 Austria EU	
11. ISO 9001	
ISO 9001	
2. 表面处理	
3. surface finishment kinds available	
4. 重量	
5. 数量	
6. 其他	
7. 认证	
ISO 9001	
OEM	