

Inspection Report







Report No.: XYKD-140507
Supplier : XY-GLOBAL

Inspection Date: 3th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKD-140507 Item No.5103401	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
5103401	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 CNC加工品
仕様	外径φ100mm 長さ100mm
材質	ADC12
表面処理	ニッケルメッキ
公差	±0.01mm
MOQ	100個
納期	受注後20-25日
梱包	10個/箱
備考	1. Name: OEM加工品 2. Process: CNC加工 3. Material: ADC12 A380 4. Surface: ニッケルメッキ 5. Tolerance: ±0.01mm 6. 数量: 100個 7. Specification: OEM仕様 8. 納期: 25-30日 9. 付属品: 付属品あり 10. 規格: Austrial EU 11. ISO 9001 ISO 9001:2015 2. 表面処理: 仕上げ 3. 表面処理: 仕上げ 4. 公差: ±0.01mm 5. 数量: 100個 6. 納期: 25-30日 7. 梱包: 10個/箱 ISO 9001 OEM加工品