

Inspection Report

Report No.: XYN-140517
Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYN-140517 Item No.XY-140430	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140430	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	铝合金 CNC 加工 OEM 定制
规格	ADC12 A380
材质	铝合金
用途	汽车零部件
加工工艺	CNC 加工
表面处理	阳极氧化
公差	±0.01mm
MOQ	1000 件
交货期	T/T 50% 预付款, 50% 尾款
包装	原厂包装
认证	ISO 9001
其他	
1.Name	铝合金 CNC 加工 OEM 定制
2.Process	CNC 加工
3.规格	ADC12 A380
4.Surface	阳极氧化
5.Tolerance	±0.01mm
6.数量	1000 件
7.Specification	OEM 定制
8.交货期	25-30 天
9.其他	accessories
10.认证	Austrial EU
11.&NBSP	ISO 9001
其他	
ISO	10 级
2.表面	阳极氧化
3.sureface	finishment kinds available
4.数量	4 件
5.公差	
6.交货期	6 天
7.其他	
其他	
&NBSP	
其他	
ISO	9001
其他	
OEM	定制