

Inspection Report

Report No.: XYI-140903
 Supplier : XY-GLOBAL

Inspection Date: 25th Sep, 2014
 Inspector: Alex

Inspection only for: PO : XYI-140903 Item No. COIN_MASS_PRODUCTION	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
COIN_MASS_PRODUCTI ON	2000Set	100% inspection	0pcs	No failure	2000Set

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 32% inspection.

Digital photo records :



1. Packing

2. Packing



3. Product compared

4 Product compared



5. Product compared

6. Product compared



7. Product: OK

8. Product: OK

000000	CNC 0000000000CNC00000000000000 00000000000000CNC0000000000CNC0000 00 00CNC000000000000000000CNC000000CNC
000000	000AL6061 AL6065AL6063AL7075SUS304SUS303SUS316POM00
000	0000000000
0000	00000000 00000000000000000000000000
000000	0000000000000000
0000	CNC00CNC 000000
000000	000000000000gague000000000000 000 0000000000 000000000000000000000000000000000000 0000000000
MOQ	00
00/00	+/- 0.01000000
000	T / T 5050T / T000000000;00
00000000	CNC000000CNC000CNC000CNC000 000000000000-00000000000000 00
00000000	0000000000000000 0000000000000000CNC0000000 000000
000	000000
00	20-25T / T 50000000
000000	CNC00000000
1.Name 0000000000OEM CNC00000000	
2.Process0000000000CNC000000	
3.MaterialAL6061 AL6065AL6063AL7075POM00	
4.Surface0000000000000000000000nickle000000 00000000	
5.Tolerance000+/- 0.010000000000000000	
600000000000100000	
7.SpecificationOEMserice00000000000000	
8.000000000000000000253000	
9.0000000000CNC0000000000000000 00accessoried000000000000	
10.0000000000000000AustrialEU00	
11.000ISO 9001	
0000 00	
ISO001. 10000000	
2.00000000000000000000	
3. surefacefinishment0000kindlsavailable00	
0000000000000004	
5.000000	
00006.0000	
7.0000000000000000	
0000-0000	
CNC000000000000000000000000000000	
CNC00000000000000	
CNC0000000000ISO9001	
CNC000000000000000000	
CNC0000000000OEM0000000000	