

Inspection Report

Report No.: XYK-140620
 Supplier : XY-GLOBAL







Inspection Date:9th Aug-, 2013
 Inspector:Alex

Inspection only for: PO . XYK-140620	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140620	1000PCS	3% inspection	0pcs	No failure	1000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
形状	形状
数量	数量
公差	公差
表面処理	CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品
MOQ	MOQ
単位	単位
納期	T / T 50 50 T / T
備考	CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品 CNC加工品
品名	品名
単位	20-25 T / T 50
備考	CNC加工品
1. Name	OEM CNC加工品
2. Process	CNC加工品
3. Material	AL6061 AL6065 AL6063 AL7075 POM
4. Surface	nickle
5. Tolerance	+/- 0.01
6. Quantity	100
7. Specification	OEM service
8. Lead time	25 30
9. CNC	accessories
10. Austrian	EU
11. ISO 9001	
ISO	1. 10
2. surface	finishment kinds available
3. surface	4
5. surface	
6. surface	
7. surface	
備考	
CNC加工品	
CNC加工品	
CNC加工品	ISO9001
CNC加工品	
CNC加工品	OEM