

**Inspection Report**

Report No.: XYSK-140625  
Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> July, 2014  
Inspector: Leo

Inspection only for: PO . XYSK-140625    Item No. XY31SY021	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY021	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product



3. Product

4 Product



5. Product:

6. report

