

**Inspection Report**

**Report No.:** XYFA-130805  
**Supplier :** XY-GLOBAL

**Inspection Date:** 1<sup>st</sup> Sep-, 2013  
**Inspector:** LEO

|  |                                   |
|--|-----------------------------------|
| Inspection only for:<br>PO . XYFA-130805      Item No.400-01-085 | <u>Inspection Result:</u><br>PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size     | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| 400-01-085  | 6000pcs       | 100% inspection | 0pcs         | No failure          | 5000pcs         |

|  |
|--|
| <b>Appearance Inspection :</b><br>No failure.  |
| <b>Dimension Inspection:</b><br>No failure , below measurement report for reference. |
| <b>Assembly Test:</b><br>No failure  |
| <b>Inspection Summary</b><br>The inspection sample plan is 100% inspection.          |

|   |   |
|---|---|
| Digital photo records :   |   |
|   |   |
| 1. Packing  | 2. Product:   |
|  |  |
| 3. Product:   | 4. Product:   |
|  |  |
| 5. Product :  | 6. Product :  |

