

**Inspection Report**

**Report No.:** XYBA-140920  
**Supplier :** XY-GLOBAL

**Inspection Date:** 18<sup>th</sup> Oct, 2014  
**Inspector:** LEO

Inspection only for: PO . XYBA-140920    Item No. XY21ZC013	<b>Inspection Result:</b> PASS
----------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC013	2000PCS	7% inspection	0pcs	No failure	2000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

