

**Inspection Report**

Report No.: XYK-140608  
 Supplier : XY-GLOBAL






Inspection Date:10<sup>th</sup> Sep-, 2014  
 Inspector:Alex

Inspection only for: PO . XYK-140608	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140608	1000PCS	3% inspection	0pcs	No failure	1000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

