

□□□□□□□□□□□□□□□□□□□□

Inspection Report

Report No.: XYS-130329
Supplier : XY-GLOBAL


Inspection Date: 27th Apr, 2013
Inspector: Leo

Inspection only for: PO . XYS-130329 Item No.XY-120096	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-120096	500PCS	10% inspection	0pcs	No failure	500pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

