

□□□□□□mechanical□□□□

**Inspection Report**

**Report No.:** XYS-140213 -V1  
**Supplier :** XY-GLOBAL

**Inspection Date:** 7<sup>th</sup> Mar-, 2014  
**Inspector:** LEO

<b>Inspection only for:</b> PO . XYS-140213	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
BOTTOM	163PCS	100% inspection	0pcs	No failure, good condition	163pcs
TOP	163PCS	100% inspection	0pcs	No failure, good condition	13pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Packing
	
3. Packing	4. Product: BOTTOM
	
7 Product: TOP	8. Product: TOP
	
11 Product: TUBE	12 Product: TUBE

品名	铝合金 铝合金
品名	ADC12 A380
品名	铝合金
品名	铝合金
品名	CNC 铝合金
品名	铝合金 gague
MOQ	100
公差	+/- 0.01
交期	T / T 50% T / T
品名	CNC 铝合金
品名	铝合金
品名	铝合金
品名	20-25 T / T 50
品名	铝合金
1.Name	OEM
2.Process	CNC
3.	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessoried
10.	Austrial EU
11.	ISO 9001
	ISO 10
	2
	3 sureface finishment kinds available
	4
	5
	6
	7
	ISO 9001
	OEM