

**Inspection Report**

Report No.: XYSK-140606  
 Supplier : XY-GLOBAL

Inspection Date: 2<sup>th</sup> July, 2014  
 Inspector: Leo

Inspection only for: PO . XYSK-140606 Item No. XY31SY006	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY006	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :																									
																									
1. Packing	2. Product																								
																									
3. Product	4 Product																								
	 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd <table border="1"> <tr> <td>Inspection Report No.</td> <td>XYSK-140606</td> <td>Product Name</td> <td>XY31SY006</td> <td>Inspection Date</td> <td>2014.7.2</td> </tr> <tr> <td>Client</td> <td>XY-GLOBAL</td> <td>Lot No.</td> <td>1407020001</td> <td>Inspector</td> <td>Leo</td> </tr> <tr> <td>Inspector</td> <td>Leo</td> <td>Sample Size</td> <td>120</td> <td>Defect Found</td> <td>0</td> </tr> <tr> <td>Inspection Result</td> <td>PASS</td> <td>Defect Description</td> <td colspan="3">No defect found.</td> </tr> </table>	Inspection Report No.	XYSK-140606	Product Name	XY31SY006	Inspection Date	2014.7.2	Client	XY-GLOBAL	Lot No.	1407020001	Inspector	Leo	Inspector	Leo	Sample Size	120	Defect Found	0	Inspection Result	PASS	Defect Description	No defect found.		
Inspection Report No.	XYSK-140606	Product Name	XY31SY006	Inspection Date	2014.7.2																				
Client	XY-GLOBAL	Lot No.	1407020001	Inspector	Leo																				
Inspector	Leo	Sample Size	120	Defect Found	0																				
Inspection Result	PASS	Defect Description	No defect found.																						
5. Product:	6. report																								

