

□□□□□□□□□□□□□□□□□□□□□□□□□□□□

### Inspection Report

**Report No.:** XYS-130729  
**Supplier :** XY-GLOBAL

**Inspection Date:** 20<sup>th</sup> Aug, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130729 Item No.XY-1302130	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-1302130	<b>2000PCS</b>	5% inspection	0pcs	No failure	2000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 ADC12 A380 OEM
規格	ADC12 A380
材質	ADC12
用途	自動車用部品
加工方法	CNC
公差	+/- 0.01
MOQ	1000
納期	約 20-25 日
備考	
1.Name	ADC12 A380 OEM
2.Process	CNC
3.規格	ADC12 A380
4.Surface	nickle
5.Tolerance	+/- 0.01
6.数量	1000
7.Specification	OEM
8.納期	25-30 日
9.付属品	accessories
10.認証	Austrial EU
11.&NBSP	ISO 9001
ISO	10
2.	
3 surface	finishment kinds available
4.	
5.	
6.	
7.	
ISO	
&NBSP	
ISO	9001
OEM	