

Inspection Report

Report No.: XYS-130318
 Supplier : XY-GLOBAL

Inspection Date: 20th Apr, 2013
 Inspector: Leo

Inspection only for: PO . XYS-130318 Item No.XY-120116	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-120116	5000PCS	10% inspection	0pcs	No failure	5000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing	2. Product
3. Product	4 Product
5. Product:	6. Product:

