

**Inspection Report**



Report No.: XYSL-130519  
 Supplier : XY-GLOBAL

Inspection Date: 17<sup>th</sup> Jun, 2013  
 Inspector: Leo

Inspection only for: PO . XYSL-130519 Item No. XY11SL011	Inspection Result: <b>PASS</b>
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11SL011	6000PCS	5% inspection	0pcs	No failure	6000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6. The test report

