

Inspection Report

Report No.: XYSL-140605
 Supplier : XY-GLOBAL


Inspection Date: 2th Jul, 2014
 Inspector: Leo

Inspection only for: PO . XYSL-140605 Item No. XY11WD029	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD029	8000PCS	5% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



3. Product	4 Product
5. Product:	6. The test report

