

Inspection Report

Report No.: XYSK-140530
 Supplier : XY-GLOBAL

Inspection Date: 28th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYSK-140530 Item No. XY11WD027	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD027	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection :
No failure.
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Dimensions report

Company	Company Name: OEM
Material	ADC12/A380
Process	CNC
Surface	nickle
Tolerance	+/- 0.01
MOQ	
Lead Time	T / T 50
Payment Terms	T / T 50
Quality Control	ISO 9001
Shipping	Austrial EU
Other	accessoried
ISO	ISO 9001
Surface Finish	finishment kinds available
Lead Time	
Payment	
Quality	
Shipping	
Other	
ISO	ISO 9001
Quality	
OEM	