

**Inspection Report**

**Report No.:** XYN-140521  
**Supplier :** XY-GLOBAL

**Inspection Date:** 16<sup>th</sup> Jun, 2014  
**Inspector:** Ken

Inspection only for: PO . XYN-140521 Item No.XY-142037	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-142037	<b>8000PCS</b>	1% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b>
No failure.
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

