

Inspection Report

Report No.: XYGA-150320
 Supplier : XY-GLOBAL

Inspection Date: 23th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYGA-140320 Item No. XY21ZC057	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC057	8000pcs	7% inspection	Opcs	No failure	8000pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

ชื่อ	cnc ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC
วัสดุ	อลูมิเนียม AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
ขนาด	ตามแบบ
ความละเอียด	± 0.01mm
MOQ	100 ชิ้น
ราคา	ตามแบบ
ระยะเวลา	20-25 วัน T / T 50 วัน
บริการ	CNC ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC ผลิตชิ้นงาน CNC
มาตรฐาน	ISO 9001
การรับประกัน	1 ปี
การชำระเงิน	20-25% T / T 50%
การขนส่ง	CNC ผลิตชิ้นงาน
1. Name	ชื่อ OEM CNC
2.	ผลิตชิ้นงาน CNC
3. Material	AL6061 AL6065 AL6063 AL7075 POM
4.	ตามแบบ
5.	±0.01mm
6.	100 ชิ้น
7.	OEM service
8.	25-30 วัน
9.	CNC ผลิตชิ้นงาน
10.	Austrial EU
11.	ISO 9001
ชื่อ	
1. ISO	10
2.	
3.	
4.	
5.	
6.	
7.	
ชื่อ	
CNC	ผลิตชิ้นงาน
CNC	ผลิตชิ้นงาน
CNC	ISO9001
CNC	ผลิตชิ้นงาน
CNC	OEM ผลิตชิ้นงาน

[ผลิตชิ้นงาน Oem ผลิตชิ้นงาน](#)