

Inspection Report

Report No.: XYDA-150303
Supplier : XY-GLOBAL

Inspection Date: 1th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYDA-150303 Item No. XY31CY023	Inspection Result: PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY023	23000PCS	1% inspection	0pcs	No failure	23000pcs

Appearance Inspection :
No failure,

Dimension Inspection:
No failure , below measurement report for reference.

Assembly Test:
No failure

Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

